

Any Spark Can Cause A Wildfire

Use **CAUTION** When Welding and Grinding.

- Keep area clear of vegetation.
- Have a spotter watch for sparks.
- Keep water and a fire extinguisher nearby.
- Wet down work area.
- Avoid welding during Red Flag conditions or on windy days.

For more information please visit:
<http://tfsweb.tamu.edu>

